

September 23, 2025

Mayor Guy Titus Board of Public Works and Safety 10 South State Street Greenfield, IN 46140

Re: WWTP Improvements Project: Certificate of Substantial Completion

Mayor and Board Members,

Commonwealth Engineers, Inc. has recommended approval of the Certificate of Substantial Completion for the WWTP Improvements Project. Substantial Completion for the project was achieved on February 13, 2025. As of February 13, 2025, the WWTP was operational, and the City was receiving beneficial use of the project. The number of items on the initial punch list warranted delaying the issuance of the certificate until the items were reduced to a manageable punch list. FA Wilhelm has been working over the past several months to address many of these items, with only a handful remaining to be corrected.

At this time, I am requesting the Board's acceptance of the recommendation from Commonwealth Engineers, Inc. for the approval of the WWTP Improvements Project Certificate of Substantial Completion for FA Wilhelm Construction. Please let me know if you have any questions or need any additional information regarding this request.

Best Regards,

Nicholas Dezelan, CHMM, ASP Wastewater Utility Manager

#### **CERTIFICATE OF SUBSTANTIAL COMPLETION**

Owner: Engineer: Contractor: Project: Contract Name:	City of Greenfield Commonwealth Engineers, Inc. F.A. Wilhelm Construction Wastewater Treatment Plant Improv Wastewater Treatment Plant Improv	-	S20046
This $\square$ Preliminary	oxtimes Final Certificate of Substantial Com	pletion applies to:	
oxtimes All Work $oxtimes$	The following specified portions of the	Work:	
*Applies to WV	VTP Improvements work and does not	include demolition work	
Date of Substantial	Completion: February 13, 2025		
Contractor, and Eng the Work or portion Contract pertaining of Substantial Comp	this Certificate applies has been inspegineer, and found to be substantially on thereof designated above is hereby east to Substantial Completion. The date of pletion marks the commencement of the estimated by the Contract.	omplete. The Date of Substant established, subject to the prov of Substantial Completion in th	ial Completion o visions of the e final Certificate
inclusive, and the fa	is to be completed or corrected is atta- ailure to include any items on such list plete all Work in accordance with the C	does not alter the responsibili	
	ntractual responsibilities recorded in t er and Contractor; see Paragraph 15.0	•	roduct of mutual
utilities, insurance,	between Owner and Contractor for se and warranties upon Owner's use or c at as amended as follows:		
Amendments to Ov	vner's Responsibilities: $oxtimes$ None $oxtimes$ As	follows:	
Amendments to Co	ntractor's Responsibilities: ⊠ None □	As follows:	
Warranty Perio	od*,		
* One year warra	inty inspection to be completed on <u>Jar</u>	uary 13, 2026.	
The following docu Punch List	ments are attached to and made a par	t of this Certificate:	

Documents, nor is it a release of Contractor's obligation to complete the Work in accordance with the Contract Documents.

Engineer: Commonwealth Engineers, Inc.

By (signature):

Name (printed):

Title:

P.E.

Contractor: F.A. Wilhelm Construction

By (signature):

Name (printed):

Title:

Contractor: F.A. Wilhelm Construction

By (signature):

Name (printed):

This Certificate does not constitute an acceptance of Work not in accordance with the Contract

#### F.A. Wilhelm Construction

Item No.	Work Area	Work Item Description	Es	stimated Value to Complete	etainage Amount to Withhold (200% of Estimated Value	Notes	Date Completed
1	GENERAL / ADMINISTRATIVE	Complete and Submit As-built Drawings		Full Retainage	Full Retainage		
2		Remove and Replace Metal Roofs	\$	700,000.00	\$ 1,400,000.00	Metal roofs, gutters, downspouts, and ancillary components to be inspected during and after installation	
3		Finalize costs for City furnished power for Contractor use	\$	25,000.00	\$ 50,000.00		
4		Finalize costs for City furnished water for Contractor use	\$	25,000.00	\$ 50,000.00		
5		Project Demobilization	\$	175,000.00	\$ 350,000.00		
6	SITE WORK / STRUCTURES	Final Site Grading and Restoration	\$	250,000.00	\$ 500,000.00	Remaining scope too extensive to itemize	
7		Paving	\$	-	\$ -	Scheduled Pay Item	
8		Site Fencing & Gates	\$	-	\$ -	Scheduled Pay Item	
9		Remove stone at laydowns, regrade, and seed	\$	20,000.00	\$ 40,000.00		
10		Install chimney seals for manholes and test	\$	18,000.00	\$ 36,000.00		
11		Coordinate final inspection of manholes with City	\$	2,000.00	\$ 4,000.00		
12		Adjust manhole grades between Headworks and SBR	\$	1,000.00	\$ 2,000.00		
13		Grout lifting lugs in the precast top for Structure No. 105			\$ -	REMOVED FROM LIST	X
14		Structure No. 105 - Top not sealed	\$	150.00	\$ 300.00		
15		Structure No. 105 - Waterproofing membrane pulling away and blocking flowline at 42" 90 bend drop pipe	\$	3,000.00	\$ 6,000.00		
16		Manhole No. 114 has a flashlight on bench wall	\$	100.00	\$ 200.00		
17		Manhole No. 123 - Casting not sealed	\$	150.00	\$ 300.00		
18		Structure No. 104 - Grout needs redone	\$	250.00	\$ 500.00		
19		Structure south of Structure No. 206 - Remove foam around pipe and grout	\$	250.00	\$ 500.00		
20		Add stormwater detention tank structure to as-built drawings	\$	-	\$ -		
21		City could not evaluate Manholes 100, 101, 102, 104, 116, 117 due to grading	\$	1,500.00	\$ .3 000 00	Coordinate final inspections after grading work is complete	
22		Move MH 100 and 101 on as-builts to show updated effluent pipe	\$	-	\$ -		
23		Demo existing vault on north side of Structure L	\$	3,000.00	\$ 6,000.00		
24		Remove and replace sections of cracked sidewalk around the SBR	\$	3,500.00	\$ 7,000.00		
25		Extend sidewalk around the south side of the 42" influent vertical stand pipe			\$ -	REMOVED FROM LIST	X
26		Install bollards on west side of retaining wall at effluent meter pit			\$ -	REMOVED FROM LIST	X
27		Valve pit	\$	2,500.00	\$ 5,000.00	Northside of storage barn needs replaced	

#### F.A. Wilhelm Construction

Date: 9/18/2025

Item No.	Work Area	Work Item Description	E	stimated Value to Complete		Retainage Amount to Withhold (200% of Estimated Value	Notes	Date Completed
28		Repair/Replace Existing Storm Line and Outfall	\$	5,000.00	\$	10,000.00	NE corner of old plant	
29		Reducing fittings on gas piping are required to be eccentric per specifications	\$	2,500.00	\$	5,000.00		
30		Loose conduit and seal tight fittings throughout the treatment plant, fittings required to be installed/tightened per UL 514	\$	10,000.00	\$	20,000.00		
31	ADMINISTRATION BUILDING - EXTERIOR	Coordinate with City to finish doors	\$	1,000.00		-		
32		Clean HVAC units	\$	200.00	_			
33		Provide City with Hydrant Keys	\$	250.00	\$	500.00		
34		Trim bituminous at HVAC duct work - West side of building	\$	100.00	\$	200.00		
35		Prep and paint rusting conduits at HVAC equipment	\$	100.00	\$	200.00		
36		Reroute HVAC drains to off the equipment pad	\$	500.00	\$	1,000.00		
37		Touch up scratches on top of HVAC equipment	\$	200.00	\$	400.00		
38		Repair damaged curb sections	\$	500.00	\$	1,000.00		
39		Discolored block in multiple locations - clean	\$	3,500.00	\$	7,000.00		
40		Replace broken downspout transitions	\$	250.00	\$	500.00		
41		Cracked mortar above east entrance	\$	200.00	\$	400.00		
42		Redo caulk at east entrance door	\$	200.00	\$	400.00		
43		Redo storm line holding water on west side of building	\$	10,000.00	\$	20,000.00		
44		Clean masonry at NW door	\$	200.00	\$	400.00		
45		Redo caulk at middle door - north side	\$	200.00	\$	400.00		
46		Patch cast stone at gutter south of Lab Entry door	\$	150.00	\$	300.00		
47		Damp block at middle door - north side	\$	1,000.00	\$	2,000.00		
48		Gaps in mortar above break room windows	\$	250.00	\$	500.00		
49		Change caulk to match sills at pedestals	\$	1,000.00	\$	2,000.00		
50		Fill gaps beneath lintel on south side of building	\$	250.00	\$	500.00		
51	ADMINISTRATION BUILDING - INTERIOR GENERAL	Above Ceiling - Re-route control wires from above plenum walkway, route wiring below walkway	\$	1,500.00	\$	3,000.00		
52		Install project plaque	\$	2,500.00	\$	5,000.00		
53	ADMINISTRATION BUILDING - INTERIOR, LAB ENTRY	Wall base below service window	\$	150.00	\$	300.00	Paint needs removed, touch up wall	
54		Light switch, exterior door	\$	150.00	\$	300.00	Not flush with wall	
55		Touch up paint	\$	500.00	\$	1,000.00	Entire room	
56		Service Window	\$	150.00	\$	. <b>31111 (111)</b>	Paint splatter needs removed, touch up around window	

9/18/2025

Item No.	Work Area	Work Item Description	E	stimated Value to Complete	Retainage Amount to Withhold (200% of Estimated Value	Notes	Date Completed
57	ADMINISTRATION BUILDING - INTERIOR, MULTIPLE ROOMS	Block wall near ceiling	\$	500.00	\$ 1,000.00	Touch up paint	
58		Floor transition at wall base	\$	1,500.00	\$ 3,000.00	Clear coat issue, dull appearance	
59		Flooring issue	\$	1,500.00	\$ 3,000.00	Repair damaged spots throughout building	
60		Touch up paint all walls	\$	1,000.00	\$ 2,000.00		
61	ADMINISTRATION BUILDING - INTERIOR, MENS RESTROOM	East door	\$	150.00		Paint edge above caulk to match wall	
62		East door	\$	150.00		Paint on floor	
63		Trim board by lockers	\$	300.00	\$ 600.00	Needs caulked/painted	
64	ADMINISTRATION BUILDING - INTERIOR, WOMENS RESTROOM	Lockers	\$	150.00	\$ 300.00	Paint splatter needs removed	
65	ADMINISTRATION BUILDING - INTERIOR, LAUNDRY ROOM	Repairs by W/H	\$	200.00	\$ 400.00	Needs painted	
66		Light	\$	200.00	\$ 400.00	Appears to not be seated properly	
67	ADMINISTRATION BUILDING - INTERIOR, MUD ROOM	Trim board by lockers	\$	200.00	\$ 400.00	Needs caulk; paint trim to match wall	
68	ADMINISTRATION BUILDING - INTERIOR, ENTRY	Service Window	\$	150.00		Paint caulk	
69		Interior Door	\$	300.00		Catching at the top, needs adjusted	
70		Exterior Frames and Doors	\$	500.00	\$ 1,000.00	Need painted	
71	ADMINISTRATION BUILDING - INTERIOR, MECHANICAL CLOSET (EAST)	Label panel	\$	150.00	\$ 300.00		
72		Touch up paint above switch	\$	150.00	\$ 300.00		
73	ADMINISTRATION BUILDING - INTERIOR, ELECTRICAL STORAGE	Air intakes need sealed	\$	300.00	\$ 600.00		
74		Gas line loose/not attached to pipe	\$	200.00	\$ 400.00	Needs to be secured; touch paint as needed	
75		Door not closing completely	\$	300.00	\$ 600.00	Latch plate is hitting the door jamb	
76		Paint north wall	\$	300.00			
77		Dents south of doorway	\$	300.00	\$ 600.00		
78	ADMINISTRATION BUILDING - INTERIOR, SCADA / CONTROL ROOM	Paint door and frame	\$	300.00	\$ 600.00		
79	ADMINISTRATION BUILDING - INTERIOR, LAB	Hallway Door	\$	500.00	\$ 1,000.00	Not plumb	
80	FLEX OFFICE	Exterior Door	\$	500.00	\$ 1,000.00	Not plumb	

#### F.A. Wilhelm Construction

Item No.	Work Area	Work Item Description	E	stimated Value to Complete	F	Retainage Amount to Withhold (200% of Estimated Value	Notes	Date Completed
81	ADMINISTRATION BUILDING - INTERIOR, CONFERENCE ROOM	Door	\$	500.00	9	1,000.00	Doesn't always close, needs adjusted	
82		Middle pane of south window has a bubble in it	\$	500.00	9	1,000.00		
83	ADMINISTRATION BUILDING - INTERIOR, FILE ROOM	Ceiling in SE corner	\$	300.00	9	600.00		
84		Touch up paint door and frame	\$	150.00	9	\$ 300.00		
85	ADMINISTRATION BUILDING - INTERIOR, LAB MECHANICAL ROOM	Paint caulk in corner	\$	150.00	9	300.00		
86		Paint above outlet by W/H	\$	150.00	9	\$ 300.00		
87		Touch up paint door and frame	\$	150.00	9	\$ 300.00		
88		Backflow Preventer	\$	300.00	9	600.00	Modify insulation to allow access to valves	
89	ADMINISTRATION BUILDING - INTERIOR, LAB STORAGE	Touch up paint around water lines	\$	150.00	9	300.00		
90		Caulk wall/floor joint	\$	200.00	9	\$ 400.00		
91		Caulk wall penetrations	\$	200.00	9	\$ 400.00		
92	ADMINISTRATION BUILDING - INTERIOR, HALLWAY	Flooring issue at sequencing patch	\$	2,000.00	9	4,000.00	Needs addressed again	
93		Flooring	\$	1,500.00	9	3,000.00	Repair damaged spots throughout building	
94	ADMINISTRATION BUILDING - INTERIOR, BREAK ROOM	Sink and drinking fountain / bottle fill station has rust on the edges	\$	750.00	9	1,500.00		
95	INFLUENT PUMP STATION ELECTRICAL BUILDING - INTERIOR	Coordinate with City to finish doors	\$	500.00	9	1,000.00		
96		Final Clean Building	\$	500.00	9	1,000.00		
97		Caulk <del>masonry wall to floor joints</del> expansion joint where slab meets wall	\$	250.00	9	500.00		
98		Tighten ABB covers	\$	150.00	9	\$ 300.00		
99		Fire alarm panel	\$	150.00			Loose conduit from fitting in floor	
100		Flooring transition to wall	\$	300.00	9	600.00	Grout by O/H door	
101		Influent pumping station wet well cleaning cycle programming	\$		9	-	Change Order Scope	
102		Control panel	\$	150.00	9	300.00	Needs final clean	
103		T conduit fittings below Raw Sewage Pump VFDs are not accessible per Section 314.29(A)(B) of NEC	\$	1,500.00	9	3,000.00		

#### F.A. Wilhelm Construction

Item No.	Work Area	Work Item Description	Es	stimated Value to Complete	Retainage Amount Withhold (200% of Estimated Value		Date Completed
104	INFLUENT PUMP STATION ELECTRICAL BUILDING - EXTERIOR	Coordinate with City to finish doors	\$	500.00	\$ 1,000.0	0	
105		Discolored masonry walls - clean	\$	1,000.00	\$ 2,000.0	0	
106		Paint block at overhead door	\$	250.00	\$ 500.0	0	
107		Grind, rub, and paint opening at overhead door	\$	500.00	\$ 1,000.0	0	
108		Additional supports for heat pump lines	\$	200.00	\$ 400.0	0	
109		Additional LP conduit supports	\$	100.00	\$ 200.0	0	
110		Fill gaps in insulation for heat pump lines	\$	150.00	\$ 300.0	0	
111		Rusty conduit above east door	\$	100.00	\$ 200.0	0	
112		A/C condensate line			\$ -	REMOVED FROM LIST	X
113		North door	\$	500.00	\$ 1,000.0	0 Rust on lights	
114		Lights/Horn	\$	250.00	\$ 500.0	0 Rust on conduit fittings	
115	INFLUENT PUMP STATION - WETWELL	Clean pump disconnects	\$	250.00	\$ 500.0	0	
116		Paint face of vent pipe 90s and install screens	\$	500.00	\$ 1,000.0	0	
117		Caulk <del>bottom joint of stairwell block expansion joint where slab</del> meets wall	\$	200.00			
118		Seal between deck and electrical boxes - north and south sides	\$	150.00	\$ 300.0	0	
119		Caulk around louver opening to flush with concrete deck to eliminate ponding	\$	200.00	\$ 400.0	0	
120		Touch up paint for vent pipes - no red	\$	150.00	\$ 300.0	0	
121		Clean grease out of middle gate sight glass	\$	100.00	\$ 200.0	0	
122		Grout slide gate frames	\$	750.00	\$ 1,500.0	0	
123		Coat anchors and plate at middle gate	\$	100.00	\$ 200.0	0	
124		Exhaust/vent piping	\$	200.00	\$ 400.0	0 Starting to show rust	
125		SW Hatch	\$	150.00	\$ 300.0	0 Needs cleaned	
126		Unistrut caps	\$	250.00	\$ 500.0	0 Needs trimmed for better fit, caps are falling off	
127	INFLUENT PUMP STATION - ARV VAULT	Grout lifting lugs in the precast lid			\$ -	REMOVED FROM LIST	X
128		Grout ARV blowoff line at precast wall - in and out	\$	100.00	\$ 200.0	0	
129		Install SS bolts and nuts at ARVs	\$	250.00	\$ 500.0	0	
130		Paint DI pipe at bolts at connection point to PVC drain	\$	100.00	\$ 200.0	0	
131		Clean bottom of vault	\$	150.00	\$ 300.0	0	
132		Paint isolation valves for ARVs	\$	150.00	\$ 300.0	0	

#### F.A. Wilhelm Construction

Item No.	Work Area	Work Item Description	Es	stimated Value to Complete	Retainage Amount to Withhold (200% of Estimated Value	Notes	Date Completed
133		Grout lifting lugs in the precast sidewall			\$ -	REMOVED FROM LIST	X
134		Touch up paint underside of 24" force mains	\$	150.00	\$ 300.00		
135	INFLUENT PUMP STATION - VALVE VAULT ACCESS BUILDING (INTERIOR)	Coordinate with City to finish doors	\$	500.00	\$ 1,000.00		
136		Grout conduit penetrations through the wall	\$	150.00	\$ 300.00	Lower level	
137		Paint grout patches in entrance	\$	150.00	\$ 300.00		
138		Seal conduit penetrations in west wall and paint	\$	150.00	\$ 300.00		
139		Exhaust fan noise - continuous			\$ -	REMOVED FROM LIST	X
140		Install kick plate for handrail on upper landing	\$	250.00	\$ 500.00		
141		Exhaust fan/louver	\$	1,500.00	\$ 3,000.00	Running at low speed/ barely opens louvers	
142		Ceiling Tile	\$	250.00	\$ 500.00	Patch hole or replace tile above stairs	
143	INFLUENT PUMP STATION - VALVE VAULT ACCESS BUILDING (EXTERIOR)	Coordinate with City to finish doors	\$	500.00	\$ 1,000.00		
144		Patch holes in block - south wall	\$	150.00	\$ 300.00		
145		Patch and paint west face of access door	\$	150.00	\$ 300.00	Unused holes drilled in the door	
146		Discolored block - Clean	\$	500.00	\$ 1,000.00		
147	INFLUENT PUMP STATION - VALVE VAULT	Paint bottom of DI pipe, 3rd pump from south wall	\$	150.00	\$ 300.00		
148		Prep and paint valve bolts on south run	\$	150.00	\$ 300.00		
149		Prep and paint face of wall pipes with all thread rods	\$	300.00	\$ 600.00		
150		Additional supports for hatch drain line	\$	100.00	\$ 200.00		
151		Final clean slab and pipe	\$	250.00	\$ 500.00		
152		Final clean trench drain and sump	\$	250.00	\$ 500.00		
153		Prep and paint bolts on ARV drain line at flanges	\$	150.00	\$ 300.00		
154		Remove concrete from conduits at NE corner	\$	250.00	\$ 500.00		
155		Groundwater leak at north wall to slab joint - injection	\$	2,500.00	\$ 5,000.00	Still leaking	
156		Paint north side of 24" force main piping at grating	\$	150.00	\$ 300.00		
157		Paint restraint rods at 24" force main vertical pipes	\$	150.00	\$ 300.00		
158		Additional conduit supports on south wall	\$	100.00	\$ 200.00		
159		Fill gap on north side of door frame with caulk to flush with wall	\$	200.00	\$ 400.00		
160		Touch up DI pipe and valves in lower level of valve vault	\$	250.00	\$ 500.00		
161		Paint restraint rods in lower level of valve vault	\$	250.00	\$ 500.00		
162		Remove test assemblies / fill ports in the lower level of the valve vault	\$	250.00	\$ 500.00	Coordinate with City	

#### F.A. Wilhelm Construction

Item No.	Work Area	Work Item Description	Es	timated Value to Complete		Retainage Amount to Withhold (200% of Estimated Value	Notes	Date Completed
163		Touch up pipe labels in the lower level of the valve vault	\$	150.00	\$	300.00		
164		Additional pipe supports for hatch drain line in the lower level of valve vault	\$	100.00	\$	200.00		
165	INFLUENT PUMP STATION - CRANE	Complete	\$	-	\$			
166	VAC SCREENING STRUCTURE	Mandrel and air test drain piping	\$	2,000.00		,		
167	HEADWORKS FACILITY	Coordinate with City to finish doors	\$	500.00	\$	1,000.00		
168		Clean construction debris from top of gates inside and outside of building	\$	150.00	\$	300.00		
169		Grind and patch rusting joint reinforcement in west face of building	\$	150.00				
170		Paint insulation for grit pump	\$	250.00	\$	500.00		
171		Touch up paint grit pump and gear box - gray	\$	100.00	\$	200.00		
172		Insulation jacketing 90 falling apart at pump discharge piping, replace dented jacketing	\$	200.00				
173		Remove tie wire at handrail	\$	50.00				
174		Loose conduits	\$	250.00	\$	500.00		
175		Lower grit pump discharge / raise midrail line at handrail as required to avoid conflict and rework insulation	\$	750.00	\$	1,500.00		
176		Tighten conduit at screen level sensor	\$	100.00	\$	200.00		
177		Touch up paint for screen motor	\$	150.00	\$	300.00		
178		Replace dented insulation on potable water line	\$	150.00	\$	300.00		
179		Fix block above north door	\$	150.00	\$	300.00		
180		Grind lintel above door and paint	\$	250.00	\$	500.00		
181		Install trim for bottom of siding	\$	500.00	\$	1,000.00		
182		Cold galv top of cut anchors at stairs - inside building	\$	150.00				
183		Patch around conduit penetrations to electrical room	\$	250.00	\$	500.00		
184		Touch up paint top of classifier - gray	\$	150.00				
185		Install cover for abandoned NPW pipe on south wall	\$	400.00				
186		Replace bent overhead door panels	\$	2,500.00	_	· ·		
187		Clean structural steel and conduits in dumpster room	\$	300.00	_			
188		Clean unit heater in dumpster room	\$	150.00				
189		Prep and caulk slab in the dumpster room	\$	250.00	_			
190		Patch mortar joints, south side of grit influent channel	\$	150.00				
191		Discolored block and mortar - Clean	\$	2,000.00		·		
192		Turn classifier drain line arrows down	\$	100.00				
193		MAU	\$	500.00	_	· ·	Rust spot and dents	
194		South stairs by grit/MAU	\$	250.00	\$	500.00	Toe plates at landings and top of stairs	

#### F.A. Wilhelm Construction

Item No.	Work Area	Work Item Description	Es	stimated Value to Complete		Retainage Amount to Withhold (200% of Estimated Value	Notes	Date Completed
195		Railings and toe plates	\$	250.00	\$	500.00	Tighten all locations; lower stairs toe plates loose	
196		South stairs by grit/MAU	\$	500.00	\$	1,000.00	Light above stairs in always on	
197		South Stairs	\$	1,500.00	\$	3,000.00	Conduits at top of hand rail need moved (MAU)	
198		Need to verify flow signal to sampler	\$	250.00	\$	500.00	Gallons/pulse needed to program sampler	
199		Grit system	\$	250.00	\$	500.00	Loose conduits and rust on paddle drive housing	
200		Grit Disconnects	\$	200.00			Check conduits	
201		Handrail	\$	500.00		· · · · · · · · · · · · · · · · · · ·	Move Unistrut from top of handrail	
202		West Door (Upper)	\$	250.00	\$		Grout corner, above door	
203		Exterior Switch Covers			\$		REMOVED FROM LIST	X
204		Screen level sensors	\$	250.00	\$		Exposed wires, should these be in conduit?	
205		Floor drains, both levels			\$		REMOVED FROM LIST	X
206		J-Box covers	\$	300.00		000.00	Check all to make sure they are tight, some still appear to be loose	
207		Stairs	\$	300.00			Top plates needed at top and at landings	
208		Odor Control	\$	250.00			Pressure gauge - internal moisture	
209		Odor Control	\$	250.00	\$	500.00	Sensor wire coiled and laying on top of unit	
210		Mechanical screen high water level programming	\$	-	\$	-	Change Order Scope	
211		Flow meter cables to be installed per C1,D1 requirements, Section 501 of NEC	\$	2,500.00	\$	5,000.00		
212		LFMC installed at multiple locations, lights, etc. LFMC is not allowed in C1,D1 areas	\$	5,000.00	\$	10,000.00		
213		Conduits required to be supported per Section 344.30(A)(B) of NEC	\$	2,500.00	\$	5,000.00		
214	HEADWORKS ELECTRICAL BUILDING	Touch up paint for ceiling trim	\$	250.00	\$	500.00		
215		Anchor generators			\$		REMOVED FROM LIST	X
216		Top off fuel for generators	\$	1,000.00				
217		Anchor transfer switches	\$	150.00	_			
218		Grind, patch lintel above door and paint	\$	200.00				
219		Tie HVAC drain into gutter	\$	400.00	_		Coordinate with City	
220		Breaker panels	\$	250.00	\$	500.00	Keys needed	
221		Breaker panels	\$	250.00			PB1 and PB1A - check conduits for tightness	
222		Wire chase below breaker panels	\$	150.00	_		Missing screws on north end of panel	
223		Transformer X1	\$	250.00	\$	500.00	Tighten conduits	

#### F.A. Wilhelm Construction

Item No.	Work Area	Work Item Description	Est	timated Value to Complete	Retainage Amount to Withhold (200% of Estimated Value	Notes	Date Completed
224		Spare conduits	\$	250.00	\$ 500.00	Label and provide as-built info	
225		SBR starter panel	\$	150.00	\$ 300.00	Provide keys	
226	SBR PIPE GALLERY - UPPER LEVEL	Coordinate with City to finish doors	\$	500.00	\$ 1,000.00		
227		Heat trace and insulate NPW lines to hydrants	\$	2,500.00	\$ 5,000.00		
228		Paint gray pipe (air), west header in gallery	\$	200.00	\$ 400.00		
229		Touch up paint bolts on 42" influent line	\$	150.00	\$ 300.00		
230		Prep and paint bolts at air line flex connectors	\$	150.00	\$ 300.00		
231		Support grating for south decant line at SBR tank 4	\$	500.00	\$ 1,000.00		
232		Install handrail	\$	-	\$ -	Change Order Scope	
233		Final clean all pipe, conduits, etc.	\$	1,000.00	\$ 2,000.00		
234	SBR PIPE GALLERY - LOWER LEVEL	Additional supports for 1" NPW at north end of gallery	\$	100.00	\$ 200.00		
235		Heat trace and insulate NPW lines to hydrants	\$	1,500.00	\$ 3,000.00		
236		Clean concrete off conduits and boxes	\$	300.00	\$ 600.00		
237		Plug hole in 24" blind flange for future decant line and paint	\$	150.00	\$ 300.00		
238		Touch up paint decant lines and bolts at wall pipes	\$	300.00	\$ 600.00		
239		Inject walls at visible leaks	\$	5,000.00	\$ 10,000.00		
240		Cut/chip concrete on south side of 2nd concrete support at floor	\$	300.00			
241		Paint top of pipe at 2nd saddle support from south end	\$	150.00	\$ 300.00		
242		Paint bottom of 42" effluent pipe, bolts, FCAs - First four sets of supports at south end of gallery	\$	300.00	\$ 600.00		
243		Paint 42" 45 degree bend - discolored and thin	\$	250.00	\$ 500.00		
244		Paint bottom sides of DI pipe at concrete supports - multiple locations	\$	150.00	\$ 300.00		
245		Clean sump at north end of gallery	\$	150.00	\$ 300.00		
246		Paint bottom of air piping - no red/no gray	\$	200.00	\$ 400.00		
247		Chip high concrete in trough at NW corner of gallery	\$	500.00	\$ 1,000.00		
248	SBR STRUCTURE - TANKS AND PIPE GALLERY TOPPING SLAB	Prep and coat rusting anchors for handrail - East side of SHT behind kick plate	\$	200.00	\$ 400.00		
249		Paint insulation at SHT decant line silver, complete caulking	\$	300.00	\$ 600.00		
250		Remove nail and coil rod at walkway and patch - Walkway north of Tank 2	\$	150.00	\$ 300.00		
251		Patch holes at NW corner of Tank 4 below sump pump discharge line	\$	2,000.00	\$ 4,000.00		

#### F.A. Wilhelm Construction

Item No.	Work Area	Work Item Description	Es	stimated Value to Complete	Retainage Amount to Withhold (200% of Estimated Value	Notes	Date Completed
252		Patch holes at SW corner of Tank 3 below sump pump discharge line	\$	2,000.00	\$ 4,000.00		
253		Patch hole in walkway at Tank 4	\$	150.00	\$ 300.00		
254		Clean concrete off slide gate and actuator at Tank 1	\$	150.00	\$ 300.00		
255		Touch up paint gate actuator at Tank 3	\$	150.00	\$ 300.00		
256		Patch around alum lines at tank penetrations	\$	400.00	\$ 800.00		
257		Remove tape from handrails	\$	250.00	\$ 500.00		
258		Remove painters tape at slide gate gauges	\$	100.00	\$ 200.00		
259		Paint exposed pipe and valves at SHT - touch up paint rods and bolts	\$	150.00	\$ 300.00		
260		Paint air valves and restraint rods - bottom of pipe including bolts	\$	150.00	\$ 300.00	Typical for all tanks	
261		Install blow off lines for air piping	\$	500.00	\$ 1,000.00	Aqua Aerobics detail	
262		Repair cracks at walkway to topping slab transition	\$	2,000.00	\$ 4,000.00	Multiple locations	
263		Grout sump pump pipe penetrations at tanks 3 and 4	\$	500.00	\$ 1,000.00		
264		Clean conduit stubs through topping slab at Tank 3 gate	\$	250.00	\$ 500.00		
265		Extend rod full nut and paint - north air valve at tank no. 4	\$	150.00	\$ 300.00		
266		Final clean topping slab - debris, nails, screws, final sweep	\$	800.00	\$ 1,600.00		
267		Pour curbs for roof hatches in the topping slab Address gap between roof slab and hatch to Owner satisfaction	\$	2,500.00	\$ 5,000.00		
268		Clean concrete off roof hatches and restore	\$	500.00	\$ 1,000.00		
269		Paint exposed pipe at NPW riser post hydrants	\$	200.00	\$ 400.00		
270		Heat trace and insulate post hydrants	\$	1,500.00	\$ 3,000.00		
271		Coat flap gates at influent baffle boxes			\$ -	REMOVED FROM LIST	X
272		Tank 3 - Remove anchors to 1" depth and patch, north of float	\$	200.00	\$ 400.00		
273		Remove screws and tie wire behind kick plate at west end of Tank 1/Tank2 walkway and patch holes	\$	150.00	\$ 300.00		
274		Patch holes (2) in deck south side of Tank 1/Tank 2 walkway	\$	150.00	\$ 300.00		
275		Patch holes in side of walkway at SE corner of Tank 4, East side and South side	\$	150.00	\$ 300.00		
276		Extend alum feed lines at SBR tanks as directed by Owner to promote alum discharge into tank versus as current on wall	\$	250.00	\$ 500.00		
277		Xypex failing joints on east side of SHT at stairs and walkway, inject	\$	400.00	\$ 800.00	Visible leaks	

Item No.	Work Area	Work Item Description	E	stimated Value to Complete		etainage Amount to Withhold (200% of Estimated Value	Notes	Date Completed
278		Xypex failing joint(s) on west side of Tank 2	\$	400.00	\$	800.00		
279		Repair spalling concrete at east end of Tank 1/Tank2 walkway	\$	150.00	\$	300.00		
280		Paint air valves and restraint rods at SHT - Touch up paint restraint rods	\$	150.00	\$	300.00		
281		Remove excess epoxy at NPW hydrant piping	\$	200.00		400.00		
282		Caulk for sidewalk to tank joint	\$	200.00	\$	400.00		
283		Touch up paint 42" influent pipe - Touch up bolts	\$	150.00	\$	300.00		
284		Final clean the sidewalk around the sludge holding tank	\$	300.00	\$			
285		Move DO and level probes and instrumentation devices to locations as shown on the plans	\$	3,000.00	\$		City cannot safely reach probes for maintenance as installed	
286		SBR 1 Sinking Decanter	\$	150,000.00	\$	·	Both decanters are sinking	
287		SBR2 Sinking Decanters	\$	150,000.00	\$	*( )( ) ( )( )( ) ( )( )	Both decanters are sinking, once decanter out of service	
288		Disconnect/Control Panels	\$	1,000.00	\$	2,000.00	Clean adhesive	
289		Tank mixer	\$	1,500.00	\$	3,000.00	Power cables float: some appear to be sinking	
290		Stair lighting	\$	2,500.00	\$	5,000.00	Not on photo cells	
291		North pipe gallery door	\$	250.00	\$	500.00	Exterior horn has open knockout	
292		North and south PG doors	\$	250.00	\$	500.00	Handles are loose, not secured to door	
293		42" Influent Pipe	\$	150.00	\$	300.00	Showing some rust in the pipe gallery	
294		Fiber/Network Panel	\$	300.00	\$	600.00	Water seeping up from conduit below panel	
295		Top Rails - Unistrut protruding above top rail is a cut hazard per OSHA, lower Unistrut below top rail Lower conduit below the top rail around narrow areas only. Replace caps everywhere.	\$	3,000.00	\$	6,000.00		
296		Receptacles - Receptacle boxes are mounted to Unistrut supports with tech screws through rear of box. Furnish manufacturer's mounting requirements showing installation meets manufacturer acceptable method of installation, or provide manufacturer confirmation that current installation is acceptable.	\$	5,000.00				
297	DIGESTER TANK	Stairs	\$	2,500.00		·	Lighting not on photo cell	
298		Stairs	\$	300.00	\$		Toe plates at landing and top needed	
299		Tank mixer	\$	1,500.00		3,000.00	Power cables float: 2 have broke loose and at least 1 more is sinking	
300		Outlet south of air header	\$	150.00	_		Conduit loose	
301		Level/float control panel	\$	150.00	\$	300.00	Missing lower screw and clip	

#### F.A. Wilhelm Construction

Item No.	Work Area	Work Item Description	Estimated Value to Complete		etainage Amount to Withhold (200% of Estimated Value	Notes	Date Completed
302		Decant flow meter		\$	-	REMOVED FROM LIST	X
303	SBR BLOWER PAD	Abandon test port at tee and plug - paint	\$ 100.00	\$	200.00		
304		Clean concrete off of conduit stubs to blower disconnects	\$ 600.00	\$	1,200.00		
305		Paint air piping support rods	\$ 150.00	\$	300.00		
306		Install handrail at north end of blower slab	\$ 2,500.00	\$	5,000.00		
307		Clean blower enclosures	\$ 500.00	\$	1,000.00		
308		Paint pipe rod supports - blue at blowers, green at air piping - touch up required	\$ 150.00	\$	300.00		
309		Prep and paint rusting anchors at the blower flex connectors	\$ 400.00				
310		Clean disconnect panels	\$ 400.00		800.00		
311		Prep and coat end of anchors for ledger at SHT	\$ 300.00				
312		Paint air piping 90 bend to SHT	\$ 150.00				
313		Tie-in gutter downspout to storm drains	\$ 250.00		500.00		
314		Remove nails in ledger at north end	\$ 100.00		200.00		
315		Unused conduit	\$ 1,000.00	\$	-	Remove if not needed	
316		All conduits	\$ 500.00		1,000.00	End of runs at blower #4, 6, 8 need additional support	
317		Blower #5	\$ 2,500.00	\$	5,000.00	Not currently operational	
318		Disconnect panels	\$ 1,500.00	\$	3,000.00	Remove/clean adhesive residue from panels	
319		Blower Housings	\$ 1,000.00	\$	2,000.00	Remove rust areas and paint	
320	EFFLUENT METER PIT	Wrap north joint of precast lid prior to backfill	\$ 150.00	\$	300.00		
321		Paint 24" riser pipe and blind / bolts for future decant line - touch up underside	\$ 150.00	\$	300.00		
322		Patch lifting lugs in precast lid		\$		REMOVED FROM LIST	X
323		Prep and paint bolts at flowmeter	\$ 150.00	\$	300.00		
324		Patch lifting lugs in the precast sections		\$		REMOVED FROM LIST	X
325		Clean flowmeter body and touch up paint	\$ 150.00		300.00		
326		Touch up paint 42" effluent pipe and bolts - underside	\$ 150.00				
327		Patch tie holes in the concrete pipe supports	\$ 250.00	\$	500.00		
328	UV STRUCTURE	Lightning protection cables - Additional supports required at SE corner column	\$ 100.00	\$	200.00		
329		Insulate NPW lines - Repair dents in jacketing, caulk at through slab location	\$ 400.00	\$	800.00		
330		Clean concrete off side of deck at the NW corner of the structure	\$ 150.00	\$	300.00		
331		Fix grout at NPW base plates	\$ 250.00	\$	500.00		

#### F.A. Wilhelm Construction

Item No.	Work Area	Work Item Description	E	Estimated Value to Complete		Retainage Amount to Withhold (200% of Estimated Value	Notes	Date Completed
332		Touch up paint NPW motors, base plates, etc.	\$	150.00	\$	300.00		
333		Final clean UV Structure	\$	300.00	\$	600.00		
334		Clean conduit stubs through the slab	\$	200.00	\$	400.00		
335		Paint ARV insulation to match jacketing	\$	150.00	\$	300.00		
336		Clean concrete off of conduits below the deck	\$	300.00	\$	600.00		
337		Replace grout at SW canopy column	\$	250.00	\$	500.00		
338		Anchor lightning protection conduit at NE corner of structure	\$	150.00	\$	300.00		
339		Add conduit support for lightning protection conduit at NW corner	\$	150.00	\$	300.00		
340		Fill tower crane conduit on east side of structure	\$	200.00	\$	400.00		
341		Extend gutter downspouts down to finish grade	\$	250.00	\$	500.00		
342		Tie-in gutter downspouts to storm pipe	\$	250.00	\$	500.00		
343		Prep and Paint face of flange for UV bypass line			\$	-	REMOVED FROM LIST	X
344		NPW system	\$	750.00	\$	1,500.00	Level sensor wires exposed, need conduit or way to protect the cables	
345		U/V control panel	\$	500.00	\$		Condensation on outside panel	
346		Effluent sampler	\$	500.00	\$	1,000.00	Needs flow signal info: gallons/pulse	
347		PDC Panel	\$	500.00	\$	1,000.00	Discoloration on southside of panel	
348		Electrical	\$	250.00	\$	500.00	Switch, outlet, and conduit mounting	
349		SG-401	\$	250.00	\$	500.00	Sight tube deformed/bent	
350	SLUDGE DEWATERING FACILITY - BUILDING EXTERIOR	Coordinate with City to finish doors	\$	500.00	\$	1,000.00		
351		Pour concrete at gutter downspouts - caulk around gutters	\$	200.00	\$	400.00		
352		Paint white spots on masonry - west side of building	\$	250.00	\$	500.00		
353		Anchor lights at SE corner of building	\$	150.00	\$	300.00		
354		Anchor lights at east side of building	\$	150.00	\$	300.00		
355		Install screen for white PVC pipe - west side	\$	150.00	\$	300.00		
356		Repair mortar joint at SE corner of building at floor	\$	150.00	\$	300.00		
357		Install trim for sides of the overhead doors. Address jagged edges on sides of the overhead doors with straight lines.	\$	4,000.00	\$	8,000.00	Cover for cut split face blocks	
358		Clean trench drain and position grates to eliminate gaps	\$	250.00	\$	500.00		
359		Paint bollard at NE corner of building	\$	150.00	\$	300.00		
360		Remove anchor on west wall of dumpster bay to 1" depth and patch	\$	100.00	\$	200.00		
361		Discolored block - Clean	\$	2,000.00	\$	4,000.00		
362		Paint block on inside of door openings	\$	250.00	_			

#### F.A. Wilhelm Construction

Item No.	Work Area	Work Item Description	E	Estimated Value to Complete		etainage Amount to Withhold (200% of Estimated Value	Notes	Date Completed
363		Install screen for small diameter pipe on east side of building	\$	150.00	\$	300.00		
364		Install fabricated seal around conveyor opening	\$	1,000.00	\$	2,000.00		
365		Replace bent enclosure pieces for overhead doors at chemical room	\$	500.00	\$	1,000.00		
366		Patch block at door openings and paint	\$	500.00	\$	1,000.00		
367		Touch up paint valve actuator - west side of dumpster bay	\$	150.00	\$	300.00		
368		Grout around upper vent pipe on south face of building - install 90 degree bend with screen	\$	500.00				
369		Trim centrifuge vent pipe, install 90 bend with screen	\$	500.00	\$	1,000.00		
370	SLUDGE DEWATERING FACILITY - ELECTRICAL ROOM	Coordinate with City to complete doors	\$	500.00	\$	1,000.00		
371		Replace north door and frame - door does not close properly and frame is cracked in multiple locations	\$	4,000.00	\$	8,000.00		
372		Remove paint on north side of PB-3	\$	150.00	\$	300.00		
373		Seal conduit and pipe penetrations through walls - SW corner of room	\$	150.00	\$	300.00		
374		Scratch in south side of sludge pump control panel	\$	150.00	\$	300.00		
375		Redo floor due to extensive discoloration and fading Review issue with manufacturer, Owner, and Engineer	\$	8,000.00	\$	16,000.00		
376		Clean top of control panels	\$	300.00	\$	600.00		
377		Insulate lines for HVAC equipment - redo to fill in gaps	\$	300.00	\$	600.00		
378		Patch wall behind junction box above SW door	\$	150.00				
379		Caulk between wall and SB-4 housekeeping pad	\$	250.00				
380		Chemical level display	\$	500.00	\$	·	Not functional, water damage	
381		Walls	\$	1,500.00	\$	3,000.00	Re-paint as needed: grout/block repairs noticeable; repaint room	
382		Exterior gas line penetration	\$	500.00	\$		Flange has rusted through, replace with different material	
383		Install properly sized conduit bushings where conduit entrance to enclosure is over drilled	\$	250.00	\$	500.00		
384	SLUDGE DEWATERING FACILITY - CHEMICAL ROOM	Coordinate with City to complete doors	\$	500.00	\$	1,000.00		
385		Redo floor due to extensive discoloration and fading Review issue with manufacturer, Owner, and Engineer	\$	15,000.00	\$	30,000.00		
386		Loose conduit connections	\$	500.00	\$	1,000.00		
387		Reroute conduit on north side of alum tank			\$	-	REMOVED FROM LIST	X
388		Cap plug valves on alum skid	\$	150.00	\$	300.00		

#### F.A. Wilhelm Construction

Item No.	Work Area	Work Item Description	Esti	imated Value to Complete	Retainage Amount to Withhold (200% of Estimated Value	Notes	Date Completed
389		Clean and mount grating	\$	250.00	•		
390		Final clean room and equipment	\$	750.00			
391		Install hose hangers at hose bibbs	\$	500.00	•		
392		Replace light at SW corner of the room - flickers	\$	500.00	\$ 1,000.00		
393		Replace cover for alum pump no. 1 panel - broken and does not latch	\$	500.00	\$ 1,000.00		
394		Loose valve on alum suction line	\$	250.00	\$ 500.00		
395		Anchor grating	\$	150.00	\$ 300.00		
396		Coat tops of rusting anchors for alum tank	\$	150.00	\$ 300.00		
397		Overhead doors	\$	1,500.00	\$ 3,000.00	Housings damaged; please address	
398		Overhead doors	\$	750.00	\$ 1,500.00	Fill/grout gap between doors and block	
399		East Interior Wall	\$	250.00	\$ 500.00	Horn missing knockout plug	
400		Spare conduit above O/H doors	\$	250.00	\$ 500.00	What's this for? Is it plugged?	
401	SLUDGE DEWATERING FACILITY - CENTRIFUGE ROOM	Coordinate with the City to complete doors	\$	500.00	\$ 1,000.00		
402		Touch up paint sludge pumps	\$	150.00	\$ 300.00		
403		Paint valves for sludge piping - Touch up required	\$	150.00	\$ 300.00		
404		Paint underside of sludge pump discharge piping	\$	150.00	\$ 300.00		
405		Rub sludge pump housekeeping pads	\$	400.00	\$ 800.00		
406		Caulk bottoms of housekeeping pads	\$	200.00	\$ 400.00		
407		Rub grout beneath sludge pumps	\$	300.00	\$ 600.00		
408		Loose conduits at sludge valves	\$	150.00	\$ 300.00		
409		Loose conduits between pumps	\$	150.00	\$ 300.00		
410		Touch up paint sludge pump discharge piping	\$	150.00	\$ 300.00		
411		Paint rusting NPW pipe support	\$	150.00	\$ 300.00		
412		Touch up paint for centrifuge equipment motor	\$	150.00	\$ 300.00		
413		Install covers for electrical boxes	\$	200.00	\$ 400.00	Multiple	
414		Redo floor due to extensive discoloration and fading-Review issue with manufacturer, Owner, and Engineer	\$	18,000.00	\$ 36,000.00		
415		Caulk masonry joint at SW corner of the centrifuge room	\$	300.00	\$ 600.00		
416		Touch up paint conveyor motor	\$	150.00	\$ 300.00		
417		Clean louver	\$	100.00	\$ 200.00		
418		Loose conduits on the south wall	\$	150.00	\$ 300.00		
419		Plug opening at conveyor motor housing	\$	150.00	\$ 300.00		
420		Add polymer pipe labels in the sump	\$	150.00	\$ 300.00		
421		Centrifuge room south door does not lock	\$	200.00	\$ 400.00		
422		Rotork cover upside down	\$	100.00	\$ 200.00		

#### F.A. Wilhelm Construction

Item No.	Work Area	Work Item Description	E	stimated Value to Complete	F	Retainage Amount to Withhold (200% of Estimated Value	Notes	Date Completed
423		Loose conduits at manifold	\$	150.00	9	\$ 300.00		
424		Conveyor #1	\$	250.00	9	\$ 500.00	Motor missing knockout plug	
425		Electrical fittings	\$	500.00	9	\$ 1,000.00	Still loose fittings, check all	
426		Stairs	\$	500.00	3	\$ 1,000.00	Toe plate at top of stairs; tighten railings	
427		PV-589	\$	250.00	5	\$ 500.00	Loose fitting	
428		Electrical drawing E1-5 requires installation of power and control conduits to future centrifuge location. Spare conduits do not appear to be installed. Provide required power conduit to future centrifuge.	\$	5,000.00	Ş	\$ 10,000.00		
429	SLUDGE DEWATERING FACILITY DUMPSTER PAD	Coordinate with City on final pipe connections for the sludge bypass vault - replace valve handle	\$	500.00	9	1,000.00		
430		Install 90 degree bend and screen for vent pipe	\$	500.00	5	\$ 1,000.00		
431		Seal off for blue wire to conveyors	\$	250.00				
432		Clean trash out of sump	\$	150.00	_	:		
433		Touch up paint conveyor motors	\$	150.00	3	\$ 300.00		
434		Cover for cleanout - Raise cleanout cover at SE side of access hatch	\$	250.00				
435	SEPTAGE RECEIVING STATION	Paint insulation to match jacketing	\$	250.00				
436		Clean trough	\$	150.00		•		
437		Additional supports for control panel stands	\$	750.00				
438		Rub exposed portion of concrete	\$	500.00	_	· · · · · · · · · · · · · · · · · · ·		
439		Replace rusting control panel anchors	\$	250.00	_			
440		Paint rusting conduits	\$	150.00	_			
441		Clean conduit stubs through the slab	\$	250.00				
442		Repair equipment insulation - bottom	\$	250.00				
443		Caulk between curb and equipment pad	\$	150.00	_			
444		Fix ponding in insulation on top of equipment	\$	150.00				
445		Clean concrete from equipment legs	\$	200.00	_			
446		Touch up paint valves	\$	150.00	_			
447		Repair cracked equipment pad for control panel	\$	400.00	3			
448		Startup/Testing	\$	1,000.00		\$ 2,000.00	Needs to be completed; haven't been able to use system due to site grading not being complete	
449		Final clean equipment slab	\$	250.00	3	\$ 500.00		
450	STRUCTURE K - EXISTING SLUDGE PROCESSING BUILDING	Paint gas piping	\$	800.00	5	1,600.00		
451		Seal around PVC pipe and conduits through the walls	\$	300.00	3	\$ 600.00		

Item No.	Work Area	Work Item Description	Es	stimated Value to Complete	V	etainage Amount to Withhold (200% of Estimated Value	Notes	Date Completed
452		Paint masonry at infill sections	\$	300.00	\$	600.00		
453		Complete pipe demo scope	\$	1,000.00	\$	2,000.00		
454		Clean concrete off conduits - west side of the building	\$	500.00	\$	1,000.00		
455		Clean masonry at core drill locations	\$	300.00	\$	600.00		
456		Finish communications panel in building	\$	1,500.00	\$	3,000.00		
457	STRUCTURE M - EXISTING CHEMICAL BUILDING	Paint gas piping	\$	250.00	\$	500.00		
458		Patch wall at PVC drain	\$	150.00	\$	300.00		
459	ADMINISTRATION BUILDING	Replace ceiling tile in hallway against west wall.	\$	100.00	\$	200.00	Outside of Rm 104 in Hallway	
460	HEADWORKS FACILITY	Repair/Modify insulation for Grit Pump	\$	1,000.00	\$	2,000.00	EXTERIOR - UPPER LEVEL	
	·	To	otal		\$	3,613,100.00		