



PRODUCT REPAIR / SERVICE ESTIMATE

Estimate #: R2023-IND-0002

Date: 1/3/2023

Page 1 of 5

Tag #: 4382

JobName: greenfeild

Customer Information

Company Name: GREENFIELD WSTWTR UTLTY

Contact:

Address

Telephone:

809 S STATE ST

Telephone:

GREENFIELD IN46140

Fax:

Email:

Following is an estimate prepared for you regarding the repair of your Flygt pump.

Product Identification

Product Number: 3300.181-3681

Serial Number: 3300.181-0360046

Model: 3300

Impeller Code: 672

HP: 75

Volts: 460

Phases: 3

Inspection Information

Inspected By: Jerry Crohn

Motor Data: Wire Configuration: U1:Red V1:Black W1:White

Megger to ground: R 00 B 000 W 000

Sensors:

Resistance through cable: RB 0.14 RW 0.14 BW 0.14

☒ FLS

Stator Condition: Good

☐ CLS

Shaft Condition: Unusable

☐ KLIX

Oil Condition: Unusable

☐ Bearing

Inspection Plugs:

☒ Cable

Hydraulic: Impeller/Propeller Condition: Unusable

Cable Condition: Good

Volute Condition: Fair

Cable Length: 25





PRODUCT REPAIR / SERVICE ESTIMATE

Estimate #: R2023-IND-0002

Date: 1/3/2023

Page 2 of 5

Tag #: 4382

JobName: greenfeild

Hydraulic Type: N

Installation

Type: T

Discharge Size: 10

☐ Control

fls yes

☐ MFV

Primary Requirement: bearings loud and seals leaking impeller is worn

Repair/Service Requirements and remarks

Upon inspection of the 3300 N style it was found to have suffered lower bearing failure causing it to be loud. Also sewage is in seal oil area from shaft being grooved as well as the impeller is worn with holes in casting.

Parts, Labor and Other Charges

Parts:

Qty	PartNo	Description	Sell Price	Total Price
1	609 62 00	RING,INSERT CI	\$3,390.64	\$3,390.64
1	606 22 36	IMPELLER,N CI	\$8,650.40	\$8,650.40
1	601 89 24	KIT,REPAIR BASIC 3300.180	\$9,511.04	\$9,511.04
1	518 89 02	DETECTOR,LEAKAGE UNIT FLS	\$316.80	\$316.80
1	504 78 11	CABLE UNIT	\$184.80	\$184.80
1	620 78 00	HOUSING,OIL CI	\$5,546.64	\$5,546.64
1		rotor shaft repair lower seal area and upper seal area kennedy	\$1,761.76	\$1,761.76
		Total Price		\$29,362.08

Labor and Other Charges:

Qty	PartNo	Description	Sell Price	Total Price
24	14-69 00 02A	LABOR,SVC FLYGT,NO TAX Z3-TP MODELS: 3000,7000,8000	\$123.20	\$2,956.80
1	14-69 00 21C	ENV FEE 11-50HP NO TAX TP ENVIRONMENTAL FEE	\$79.20	\$79.20





PRODUCT REPAIR / SERVICE ESTIMATE

Estimate #: R2023-IND-0002

Date: 1/3/2023

Page 3 of 5

Tag #: 4382

JobName: greenfeild

1	14-69 00 24B	SHOP SUPPLIES-LARGE PUMPS TP MISC SHOP SUPPLIES FOR REPAIR	\$92.40	\$92.40
3	14-69 00 02A	LABOR,SVC FLYGT,NO TAX Z3-TP MODELS: 3000,7000,8000	\$123.20	\$369.60
		Total Price		\$3,498.00

Total Price: \$32,860.08

Product Replacement

Product Number:

Estimated Delivery: Weeks

Cost of New Unit:

Description:

Terms

Please note: If additional repair requirements are identified during service, the total cost of your repair may change. Should this occur, we will contact you for approval before proceeding.

A signed Purchase Order or approval below must be received before any repair work can begin.

If repaired unit is not picked up or delivered within 5 days of completion, the repair will be invoiced.

Taxes: State, local and other applicable taxes are not included in this quotation. If tax exempt, please provide a copy of your Indiana State ST-105 Form with your order so we are able to update your Xylem Water Solutions, USA, Inc. customer file.

Time of delivery: Approx. 2-4 working weeks after receipt of order.

Validity: This Quote is valid for thirty (60) days.

Terms of payment: 100% N30 after invoice date.

Warranty: Parts used for this repair carry a 12 month warranty.

Inspection Fee: If pump is not repaired following full inspection, a fee may be charged for the inspection.

Changes: This Quote is based on the current design criteria provided to Xylem Water Solutions USA, Inc. Revisions may result in price changes.

Exclusions: This Quote includes only the items listed specified above.



Flygt Products
7615 West New York Street, Indianapolis IN 46214
PH: 317/273-4470
FX: 317/273-4480





Xylem Water Solutions USA, Inc.
Flygt Products

PRODUCT REPAIR / SERVICE ESTIMATE

Estimate #: R2023-IND-0002

Date: 1/3/2023

Page 4 of 5

Tag #: 4382

JobName: greenfeild

Terms and Conditions: The Xylem Water Solutions USA, Inc. North American Terms and Conditions of Sale apply to this order and is accessible at <http://www.xylemwatersolutions.com/scs/usa/en-us/Pages/General-Terms-and-Conditions-of-sale.aspx>. Partial billing will be made on any partial shipments. Equipment returns are subject to approval and possible re-stocking fees. Special order items (i.e. Control Panels, hatch covers) will not be accepted for return.

Thank you for the opportunity to provide this quotation. Please contact us if there are any questions.

Jerry Crohn

Phone: 317/273-4470

Fax: 317/273-4480

Email: jerry.crohn@xylem.com



Flygt Products
7615 West New York Street , Indianapolis IN 46214
PH: 317/273-4470
FX: 317/273-4480





Xylem Water Solutions USA, Inc.
Flygt Products

PRODUCT REPAIR / SERVICE ESTIMATE

Estimate #: R2023-IND-0002

Date: 1/3/2023

Page 5 of 5

Tag #: 4382

JobName: greenfeild

Customer Approval

Complete and sign this Approval and return to Xylem Water Solutions USA, Inc with, or in place of, your Purchase Order

I authorize Xylem Water Solutions USA, Inc to proceed for the amount shown above.



Repair



Replacement

Customer Name:

Customer Signature: Chuck Fewell - Mayor

Date: 1/03/2023

PO #: Greenfield WW: RSP#1

Ship To:



Will Pick Up



Deliver



Ship To

Ship/Delivery Address:

Bill To:

City of Greenfield Wastewater Utility

809 South State Street

Greenfield, IN 46140

Taxable:



Yes



No

Tax Exemption Certificate must be on file or tax will be applied to the invoice.



Flygt Products
7615 West New York Street, Indianapolis IN 46214
PH: 317/273-4470
FX: 317/273-4480

