

Indy Aerial Services, LLC

5420 East 30TH Street
Indianapolis, IN 46218

ESTIMATE

Date	Estimate#
5/8/2023	165

Bill To
Greenfield Street Department 900 West Tague Greenfield, IN 46140

Ship To
Greenfield Street Department 900 West Tague Greenfield, IN 46140

P.O. Number	Terms	Due Date	Vehicle ID
Tim		5/8/2023	S/N: AEA87011 Unit: 83229

Quantity	Description	U/M	Price Each	Amount
1	Swivel Cylinder (New Altec)	ea	4,142.86	4,142.86
1	Hydraulic Fittings		250.00	250.00
8	Hydraulic Oil (8 Gallons)	Gal	118.75	950.00
6	Labor: Diagnosis on swivel cylinder leaking hydraulic oil. Found the hydraulic swivel cylinder is leaking due to seals are dry rotted leaking hydraulic oil. Removal/ install New Swivel Cylinder (Altec) and hydraulic fittings. Fill with 8 gallons hydraulic oil.		90.00	540.00

No sales tax charged due to being the state of IN. We appreciate your business!

Subtotal \$5,882.86

Sales Tax (7.0%) \$0.00

Total \$5,882.86

Phone #	Fax #	E-mail
(317) 549-0608	(317) 549-0257	aerialservices54@yahoo.com

Altec Service Estimate

5201 W 84th Street
Indianapolis, IN, 46268
US

Customer				Service Request	
Estimate #	830284			Service Request #	5429680
Customer	GREENFIELD POWER & LIGHT			Unit Information	
Account #	14981	Payment Terms	NET 30	Customer Vehicle #	
Contact	TIM BOYK			Model	AT37G
Email				Chassis VIN #	1FDAF5HR5AEA87011
Phone		Fax		Mileage	
Mobile				Unit Serial #	0410DE11791
Altec Representative				Assy Serial #(FA)	057-16228117
Contact	Charles David Wicker			In-Service Date	03-Jun-2010
Email	David.Wicker@altec.com				
Phone		Fax			
This Estimate Expires: 20-APR-23					
Notes:					

Item	Description	Hours	Labor	Material	Expenses	Total
1	TROUBLE SHOOT HYDRAULIC LEAK/ LEAKS	3.25	\$471.25	\$0.00	\$0.00	\$471.25
2	~REPLACE ROTARY JOINT	5.00	\$725.00	\$2,078.24	\$0.00	\$2,803.24
4	~REPLACE HYDRAULIC RESERVOIR	4.00	\$580.00	\$689.62	\$0.00	\$1,269.62
5	~TOP OFF HYDRAULIC RESERVOIR	0.50	\$72.50	\$151.10	\$0.00	\$223.60
6	~PERFORM DIELECTRIC TEST	--	\$390.00	\$0.00	\$0.00	\$390.00
7	CLEAN AFFECTED AREAS OF OIL LEAK	2.00	\$290.00	\$0.00	\$0.00	\$290.00
8	REPLACE CRACKED WINDSHIELD (SUBLET)	0.00	\$0.00	\$0.00	* \$499.50	\$499.50
9	~PERFORM STRUCTURAL LOAD TEST	1.50	\$217.50	\$0.00	\$0.00	\$217.50
10	~PERFORM OPERATIONAL TEST	0.50	\$72.50	\$0.00	\$0.00	\$72.50
11	SUPPLIES AND ENVIRONMENTAL DISPOSAL FEES	0.00	\$0.00	\$0.00	* \$200.00	\$200.00
12	FREIGHT ESTIMATE	0.00	\$0.00	\$0.00	* \$2,361.82	\$2,361.82
Totals		16.75	\$2,818.75	\$2,918.96	\$3,061.32	\$8,799.03

Options:
The items listed below are NOT included in the total above

Item	Description	Hours	Labor	Material	Expenses	Total
3	REPLACE ALL HOSES FROM ROTATION AND UP	40.00	\$5,800.00	\$12,076.75	\$0.00	\$17,876.75

*This estimate is provided with the understanding that items may be discovered during the repair process that may require additional labor and/or materials to repair. Examples would include, but are not limited to, hidden damages or items that were not clearly visible or known at the time of estimate, damaged internal components, fasteners and pins that may be rusted, seized or broken.

**This estimate does not include City, County, State or Federal taxes.

***Transportation or towing of the vehicle is not included in the estimate unless specified.

****Freight charges are estimated and may be adjusted to reflect the actual cost incurred on the invoice.