



April 14, 2020

Mayor Chuck Fewell
Board of Works and Public Safety
10 South State Street
Greenfield, IN 46140

Re: Fine Screen Service Visit

Mayor and Board Members,

The fine screen at the headworks of the WWTP needs to be serviced. The controls for the equipment have not been functioning properly. We have had a local technician work on it in the past to keep it running, but at this point, I feel it would be best to have a factory trained technician from Lakeside Equipment diagnose the issue. The cost for the service visit is a flat rate of \$1,500.00. They have also quoted a replacement for the level sensor that controls when the screen runs, which is likely the cause of the main issue we have been experiencing. If required, the cost of the sensor would be \$2,466.00.

At this time, I am requesting that the Board approve the cost of the service visit and the replacement sensor, if needed, in the total amount of \$3,966.00. The estimate for the visit and sensor has been included with this request for your review. Please let me know if you have any questions or need any other information regarding this request.

Best Regards,

A handwritten signature in black ink, appearing to read "Nicholas Dezelan".

Nicholas Dezelan, CHMM, ASP
Wastewater Utility Manager

cc: Michael Fruth, Utility Director
Dan Worl, Business Services Manager

Wastewater Utility
809 South State Street: Greenfield, Indiana 46140
wwtp@greenfieldin.org
Phone 317-477-4360 Fax 317-477-4361